



To : Trust Engineering company
From : Nabil Alsaghir workshop & design office section head
Sub : Success Story Contribution

Problem

The main frame of furnace (I beam 30*30) and head tip (St. St. 310) was damaged due to direct heat (1250 C)

Solved

Repaired I beam frame by magna 303, fabricated new head tip by magna 393 and connected I beam with head tip by using magna 303

Outcome

We save about 10 operation days to export this part from outboard that means 10.000 ton of finished products (26, 000000 LE).

Finally thanks for your co-operation and best regard

Central Repair Workshop & Design office Sec. Head

Nabil Mohamed

18-01-05